

## Hafnium Tetrachloride

UN1759

SDS: SAC027


28-Feb-2020 Ver 4 NA-EN

### DANGER

May be corrosive to metals.  
Causes severe skin burns and eye damage.



Wear protective gloves/protective clothing/eye protection.  
Do not breathe dust/gas/mist.  
IF SWALLOWED: Rinse mouth. Do NOT induce vomiting.  
IF ON SKIN (or hair): Brush off loose particles from skin. Remove/ Take off immediately all contaminated clothing. Rinse skin with water/ shower.  
IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing.  
IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.



ATI, 1000 Six PPG Place  
Pittsburgh, PA 15222 USA

CHEMTREC: +1 800-424-9300

Safety data sheets and labels available at [ATImetals.com](http://ATImetals.com)

## Hafnium Tetrachloride

UN1759

SDS: SAC027


28-Feb-2020 Ver 4 NA-EN

### DANGER

May be corrosive to metals.  
Causes severe skin burns and eye damage.



Wear protective gloves/protective clothing/eye protection.  
Do not breathe dust/gas/mist.  
IF SWALLOWED: Rinse mouth. Do NOT induce vomiting.  
IF ON SKIN (or hair): Brush off loose particles from skin. Remove/ Take off immediately all contaminated clothing. Rinse skin with water/ shower.  
IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing.  
IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.



ATI, 1000 Six PPG Place  
Pittsburgh, PA 15222 USA

CHEMTREC: +1 800-424-9300

Safety data sheets and labels available at [ATImetals.com](http://ATImetals.com)

## Hafnium Tetrachloride

UN1759

SDS: SAC027


28-Feb-2020 Ver 4 NA-EN

### DANGER

May be corrosive to metals.  
Causes severe skin burns and eye damage.



Wear protective gloves/protective clothing/eye protection.  
Do not breathe dust/gas/mist.  
IF SWALLOWED: Rinse mouth. Do NOT induce vomiting.  
IF ON SKIN (or hair): Brush off loose particles from skin. Remove/ Take off immediately all contaminated clothing. Rinse skin with water/ shower.  
IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing.  
IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.



ATI, 1000 Six PPG Place  
Pittsburgh, PA 15222 USA

CHEMTREC: +1 800-424-9300

Safety data sheets and labels available at [ATImetals.com](http://ATImetals.com)

## Hafnium Tetrachloride

UN1759


SDS: SAC027

28-Feb-2020 Ver 4 NA-EN

May be corrosive to metals.  
Causes severe skin burns and eye damage.



Wear protective gloves/protective clothing/eye protection.  
Do not breathe dust/gas/mist.  
IF SWALLOWED: Rinse mouth. Do NOT induce vomiting.  
IF ON SKIN (or hair): Brush off loose particles from skin. Remove/ Take off immediately all contaminated clothing. Rinse skin with water/ shower.  
IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing.  
IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.



ATI, 1000 Six PPG Place  
Pittsburgh, PA 15222 USA

CHEMTREC: +1 800-424-9300

Safety data sheets and labels available at [ATImetals.com](http://ATImetals.com)

## Hafnium Tetrachloride

UN1759

SDS: SAC027


28-Feb-2020 Ver 4 NA-EN

### DANGER

May be corrosive to metals.  
Causes severe skin burns and eye damage.



Wear protective gloves/protective clothing/eye protection.  
Do not breathe dust/gas/mist.  
IF SWALLOWED: Rinse mouth. Do NOT induce vomiting.  
IF ON SKIN (or hair): Brush off loose particles from skin. Remove/ Take off immediately all contaminated clothing. Rinse skin with water/ shower.  
IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing.  
IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.



ATI, 1000 Six PPG Place  
Pittsburgh, PA 15222 USA

CHEMTREC: +1 800-424-9300

Safety data sheets and labels available at [ATImetals.com](http://ATImetals.com)

## Hafnium Tetrachloride

UN1759

SDS: SAC027


28-Feb-2020 Ver 4 NA-EN

### DANGER

May be corrosive to metals.  
Causes severe skin burns and eye damage.



Wear protective gloves/protective clothing/eye protection.  
Do not breathe dust/gas/mist.  
IF SWALLOWED: Rinse mouth. Do NOT induce vomiting.  
IF ON SKIN (or hair): Brush off loose particles from skin. Remove/ Take off immediately all contaminated clothing. Rinse skin with water/ shower.  
IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing.  
IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.



ATI, 1000 Six PPG Place  
Pittsburgh, PA 15222 USA

CHEMTREC: +1 800-424-9300

Safety data sheets and labels available at [ATImetals.com](http://ATImetals.com)